


REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Boramy Ith

REPORT DATE: October 13, 1993

RECEIVED: September 17, 1993

LABORATORY NUMBER: 61611

Water from Torrance Stormdrain next to 799
Sample Date: 09/17/93
P.O. Number: T & M 25998-C

Third Quarter, 1993, Analysis as Required by NPDES Permit #CA0001414

RESULTS

Total Flow, GPD	No Flow
Temperature, °F	67
pH, Units (EPA 150.1)	8.2

MILLIGRAMS PER LITER

Parameter	Method	Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	20.9
Chromium	200.7	0.01	0.02
Oil and Grease	413.1	6.0	ND
Settleable Solids (ml/L/hr)	160.5	0.20	5.0
Total Suspended Solids	160.2	4.0	59.0

*ND = Not detected, below detection limit

Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.